

**HISTORIC AMERICAN ENGINEERING RECORD**

**INDEX TO PHOTOGRAPHS**

**HAER No. WA-117**

Outlet Creek Bridge  
Sullivan Lake Ranger District Administrative Site  
Colville National Forest  
Metaline Falls Vicinity  
Pend Oreille County  
Washington

Harvey S. Rice, Photographer, November 1993

- WA-117-1 Bridge, Outlet Creek, and Sullivan Lake (in rear). View to south.
- WA-117-2 Site showing bridge (left) and dam (right). View to southwest.
- WA-117-3 Creek and bridge. View to northwest.
- WA-117-4 South elevation of bridge showing log boom across Outlet Creek. View to west.
- WA-117-5 East approach to bridge, showing dam (right). View to west.
- WA-117-6 Bridge deck from west approach, showing Sullivan Lake District Ranger Station building (left rear). View to northeast.
- WA-117-7 Bridge deck, showing dam (left) and Sullivan Lake District Ranger Station buildings (left rear). View to north.
- WA-117-8 Close view of south elevation of bridge, showing stream level gauge (right center). View to west.
- WA-117-9 South elevation of bridge, showing timber bents, piles, and cross-bracing. View to north.
- WA-117-10 Substructure of bridge, showing timber bents, piles, cross-bracing, caps, and stringers under deck. View to northeast.

HAER  
WASH  
26-METFA.V  
1-

OUTLET CREEK BRIDGE, SULLIVAN LAKE  
RANGER DISTRICT ADMINISTRATIVE SITE  
HABS NO. WA-117 (Page 2)  
INDEX TO PHOTOGRAPHS

Note: Photographs Nos. WA-117-11 and WA-117-12 are photocopies of 1934 drawings produced in the U.S. Forest Service Region 1 Office, Missoula, Montana, and now housed in the Region 6 Office, Portland, Oregon.

- WA-117-11 Photocopy of drawing. 190' TREATED TIMBER TRESTLE OVER SULLIVAN LAKE OUTLET. DRAWING NO. R-63-1.
- WA-117-12 Photocopy of drawing. 190' TREATED TIMBER TRESTLE OVER SULLIVAN LAKE OUTLET. DRAWING NO. R-63-2.
- WA-117-13 Photocopy of drawing (1983 drawing no. 33000 00-11.5, sheet 1, by J. Kenneally, U.S. Forest Service, Colville National Forest, Colville, Washington) SULLIVAN LAKE OUTLET BRIDGE RAILING.